

APPENDIX - VIII

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.

No. 10

Date : 29/03/2022

It is certified that an inspection team headed by Sri Dillip Kumar
Behera, Assistant Engineer; RWS & S Section (Name of Officers
with designation) from RWS & S Section, Banarpal (Name of
Department/Office) inspected the Kendriya Vidyalaya NO-2
Railway Colony, Raniguda, Angul (Name & Address of
the School) on 21.03.22 and found that the Kendriya Vidyalaya
NO-2 Angul (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of 01 (One) year.

Signature with Seal : 29/03/22
Asst. Engineer
Name : Dillip Kumar Behera
Designation : Assistant Engineer
RWS & S Section
Banarpal.

To

The Principal
Kendriya Vidyalaya NO-2
Angul Railway Colony, Raniguda.
(Name & Address of the Institution)